

## WEEKLY SUMMARY REPORT

---

Client:	Needham DPW	Dates:	12/30/2019 to 1/3/2020
Contract:	Rosemary Lake Dredging		
Contractor:	Maverick Construction Co., Inc.	Inspector(s) on site:	Caroline Armstrong Craig Ellis

---

### WORK COMPLETED THIS WEEK

---

- Weekly turbidity monitoring conducted on Thursday along Rosemary Brook. Fish nets inspected on Thursday by BETA.
- Fuel cubes delivered to staging area.
- On-going equipment and material mobilization.
- Evaluation of analytical data from lake sediment sampling.

### WORK ANTICIPATED FOR NEXT WEEK

---

- Weekly turbidity monitoring to be conducted along Rosemary Brook.
- Construction of lake bed staging area.
- Test pitting for Town water pipe location (Pending, date to be determined).
- Maverick to begin mobilizing treatment system.
- On-going equipment procurement and installation.

## PHOTOS

---



**Fuel Cube delivery to Staging Area**



**Lake bed with staging area in background (facing southwest)**



**Lake bed with staging area in background (facing north)**





**Lake Outfall**



**Fish Net at southern inlet**





**Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Thursday.**



**Station 1 (Petrini Property) – Turbidity and sediment depth readings taken on Thursday.**



**Station 2 (West Street) – Turbidity and sediment depth readings taken on Thursday.**